

B L A D E A N D B U C K E T R E P A I R

The Leading Edge Turbine Technologies facility has full in-house capabilities with welding, mechanical and material engineering to repair all type of turbine blades, and buckets for quality airfoil repairs. Facility features include:

- > Tip grinding to restore tip heights and radius
- > Z- notch restoration
- > Eddy current inspection
- > Full in-house materials engineering capabilities
- > Coating removal and stripping capabilities
- > Stress rupture bar testing analysis

www.leturbine.com

"Provider of Quality Turbomachinery Repair and Service"

LEADING EDGE TURBINE TECHNOLOGIES, LTD.

20120 EAST HARDY ROAD, HOUSTON, TEXAS 77073
PHONE: 281-821-2255 FAX: 281-821-7755


Leading Edge